MATERIAL SAFETY DATA SHEET

Date Printed: 04/29/2008 Date Updated: 02/01/2006

Version 2.3

Section 1 - Product and Company Information

Product Name SILICON TETRABROMIDE, 99.995%

Product Number 494100 Brand ALDRICH

Company Sigma-Aldrich Canada, Ltd Address 2149 Winston Park Drive

Oakville ON L6H 6J8 CA

Technical Phone: 9058299500 Fax: 9058299292 Emergency Phone: 800-424-9300

Section 2 - Composition/Information on Ingredient

Substance Name CAS # SARA 313 SILICON TETRABROMIDE 7789-66-4 No

Formula SiBr4

Synonyms Tetrabromosilane

Section 3 - Hazards Identification

EMERGENCY OVERVIEW

Corrosive.
Causes burns.

HMIS RATING

HEALTH: 3

FLAMMABILITY: 0
REACTIVITY: 1

NFPA RATING

HEALTH: 3

FLAMMABILITY: 0 REACTIVITY: 1

For additional information on toxicity, please refer to Section 11.

Section 4 - First Aid Measures

ORAL EXPOSURE

If swallowed, wash out mouth with water provided person is conscious. Call a physician. Do not induce vomiting.

INHALATION EXPOSURE

If inhaled, remove to fresh air. If not breathing give artificial respiration. If breathing is difficult, give oxygen.

DERMAL EXPOSURE

In case of skin contact, flush with copious amounts of water for at least 15 minutes. Remove contaminated clothing and shoes. Call a physician.

EYE EXPOSURE

In case of contact with eyes, flush with copious amounts of water for at least 15 minutes. Assure adequate flushing by separating the eyelids with fingers. Call a physician.

Section 5 - Fire Fighting Measures

FLASH POINT

N/A

AUTOIGNITION TEMP

N/A

FLAMMABILITY

N/A

EXTINGUISHING MEDIA

Suitable: Carbon dioxide, dry chemical powder, or appropriate foam.

FIREFIGHTING

Protective Equipment: Wear self-contained breathing apparatus and protective clothing to prevent contact with skin and eyes. Specific Hazard(s): Emits toxic fumes under fire conditions.

Section 6 - Accidental Release Measures

PROCEDURE TO BE FOLLOWED IN CASE OF LEAK OR SPILL Evacuate area.

PROCEDURE(S) OF PERSONAL PRECAUTION(S)

Wear self-contained breathing apparatus, rubber boots, and heavy rubber gloves.

METHODS FOR CLEANING UP

Cover with dry lime or soda ash, pick up, keep in a closed container, and hold for waste disposal. Ventilate area and wash spill site after material pickup is complete.

Section 7 - Handling and Storage

HANDLING

User Exposure: Do not breathe vapor. Do not get in eyes, on skin, on clothing. Avoid prolonged or repeated exposure.

STORAGE

Suitable: Keep tightly closed. Store in a cool dry place. Store under nitrogen.

SPECIAL REOUIREMENTS

Air and moisture sensitive.

Section 8 - Exposure Controls / PPE

ENGINEERING CONTROLS

Safety shower and eye bath. Use only in a chemical fume hood.

PERSONAL PROTECTIVE EQUIPMENT

Respiratory: Use respirators and components tested and approved under appropriate government standards such as NIOSH (US) or CEN (EU). Where risk assessment shows air-purifying respirators are

appropriate use a full-face respirator with multi-purpose combination (US) or type ABEK (EN 14387) respirator cartridges as a backup to engineering controls. If the respirator is the sole means of protection, use a full-face supplied air respirator.

Hand: Compatible chemical-resistant gloves.

Eye: Chemical safety goggles.

Other: Faceshield (8-inch minimum).

GENERAL HYGIENE MEASURES

Wash contaminated clothing before reuse. Discard contaminated shoes. Wash thoroughly after handling.

Section 9 - Physical/Chemical Properties

| Appearance | Physical State: Lic Color: Colorless Odor: Stench. | quid |
|--|--|----------------------------|
| Property | Value | At Temperature or Pressure |
| Molecular Weight pH | 347.72 AMU N/A | |
| BP/BP Range MP/MP Range Freezing Point Vapor Pressure Vapor Density Saturated Vapor Conc. SG/Density Bulk Density Odor Threshold Volatile% VOC Content Water Content Solvent Content Evaporation Rate Viscosity Surface Tension Partition Coefficient Decomposition Temp. Flash Point Explosion Limits | 153 °C 5 °C N/A N/A N/A 2.8 g/1 N/A 2.79 g/cm3 N/A | 760 mmHg |
| Flammability Autoignition Temp Refractive Index | N/A N/A N/A | |

N/A = not available

Optical Rotation

Miscellaneous Data

Section 10 - Stability and Reactivity

STABILITY

Solubility

Conditions of Instability: May decompose on exposure to moist air

Reactions to Avoid: Potassium

Conditions to Avoid: Air sensitive.

Materials to Avoid: Strong bases, Alcohols.

N/A

N/A

N/A

HAZARDOUS DECOMPOSITION PRODUCTS

Hazardous Decomposition Products: Hydrogen bromide gas, Silicon

HAZARDOUS POLYMERIZATION

Hazardous Polymerization: Will not occur

Section 11 - Toxicological Information

ROUTE OF EXPOSURE

Skin Contact: Causes burns.

Skin Absorption: May be harmful if absorbed through the skin.

Eye Contact: Causes burns.

Inhalation: Material is extremely destructive to the tissue of the mucous membranes and upper respiratory tract. May be harmful if inhaled.

Ingestion: May be harmful if swallowed.

SIGNS AND SYMPTOMS OF EXPOSURE

Material is extremely destructive to tissue of the mucous membranes and upper respiratory tract, eyes, and skin. Inhalation may result in spasm, inflammation and edema of the larynxand bronchi, chemical pneumonitis, and pulmonary edema. Symptoms of exposure may include burning sensation, coughing, wheezing, laryngitis, shortness of breath, headache, nausea, and vomiting. To the best of our knowledge, the chemical, physical, and toxicological properties have not been thoroughly investigated. Nausea, headache, and vomiting. Exposure can cause:

Section 12 - Ecological Information

No data available.

Section 13 - Disposal Considerations

APPROPRIATE METHOD OF DISPOSAL OF SUBSTANCE OR PREPARATION
Contact a licensed professional waste disposal service to dispose
of this material. Dissolve or mix the material with a combustible
solvent and burn in a chemical incinerator equipped with an
afterburner and scrubber. Observe all federal, state, and local
environmental regulations.

Section 14 - Transport Information

DOT

Proper Shipping Name: Corrosive liquid, acidic,

inorganic, n.o.s.

UN#: 3264 Class: 8

Packing Group: Packing Group II

Hazard Label: Corrosive

PIH: Not PIH

IATA

Proper Shipping Name: Corrosive liquid, acidic,

inorganic, n.o.s.
IATA UN Number: 3264
Hazard Class: 8
Packing Group: II

Section 15 - Regulatory Information

EU ADDITIONAL CLASSIFICATION Symbol of Danger: C

Indication of Danger: Corrosive.

R: 34

Risk Statements: Causes burns.

S: 26-28-27-36/37/39

Safety Statements: In case of contact with eyes, rinse immediately with plenty of water and seek medical advice. After contact with skin, wash immediately with plenty of water. Take off immediately all contaminated clothing. Wear suitable protective clothing, gloves, and eye/face protection.

US CLASSIFICATION AND LABEL TEXT

Indication of Danger: Corrosive.

Risk Statements: Causes burns.

Safety Statements: In case of contact with eyes, rinse immediately with plenty of water and seek medical advice. After contact with skin, wash immediately with plenty of water. Take off immediately all contaminated clothing. Wear suitable protective clothing, gloves, and eye/face protection.

UNITED STATES REGULATORY INFORMATION

SARA LISTED: No

CANADA REGULATORY INFORMATION

WHMIS Classification: This product has been classified in accordance with the hazard criteria of the CPR, and the MSDS contains all the information required by the CPR.

DSL: No NDSL: Yes

Section 16 - Other Information

DISCLAIMER

For R&D use only. Not for drug, household or other uses.

WARRANTY

The above information is believed to be correct but does not purport to be all inclusive and shall be used only as a guide. The information in this document is based on the present state of our knowledge and is applicable to the product with regard to appropriate safety precautions. It does not represent any guarantee of the properties of the product. Sigma-Aldrich Inc., shall not be held liable for any damage resulting from handling or from contact with the above product. See reverse side of invoice or packing slip for additional terms and conditions of sale. Copyright 2008 Sigma-Aldrich Co. License granted to make unlimited paper copies for internal use only.